

**OFFICIAL GEORGIA WOOD INFESTATION INSPECTION REPORT**

Company Name Rich Exterminators, Inc. License No. 97982  
 Address P. O. Box 465267 - Lawrenceville, Georgia 30042  
 Telephone No. (770) 682-7755 Date of Issuance 8/15/06  
 Seller Brian & Cynthia Rosenberg Inspector L. Foward Rich  
 File No. 15758 Purchaser(s) 1st Letter

**SCOPE OF INSPECTION**

An inspection of the below listed structure(s) was performed by a qualified inspector employed by this firm to determine the presence or previous presence of an infestation of the listed organisms and is not intended to be a structural report. Neither is this a warranty as to absence of wood destroying organisms. This report is subject to all conditions enumerated on the reverse side and is issued without warranty or guarantee except as provided in Rule 620-6-.03 of the Rules of the Georgia Structural Pest Control Act or subject to any treatment guarantee specified below.

Main Structure One House Only  
 Other Structures (Specify) None  
 Address of Structure(s) 3173 Little Bear Lane Buford, GA 30519

**FINDINGS**

Inspection Reveals Visible Evidence of:

|  | Active Infestation |    | Previous Infestation |    |
|--|--------------------|----|----------------------|----|
|  | YES                | NO | YES                  | NO |
| Subterranean Termites                        | ---                | X  | ---                  | X  |
| Powder Post Beetles                          | ---                | X  | ---                  | X  |
| Wood Boring Beetles                          | ---                | X  | ---                  | X  |
| Dry Wood Termites                            | ---                | X  | ---                  | X  |
| Wood Decaying Fungus (Not Molds and Mildews) | ---                | X  | ---                  | X  |

Were any areas of the structure obstructed or inaccessible?  YES  NO

If yes, list these areas (see Item 3 on reverse side of form):  
house is on a slab of poured concrete, mutation in tile

The following conditions conducive to infestation for wood destroying organisms were found at the time of inspection. The location of these conditions conducive to infestation are indicated on the attached diagram:

Remarks/Additional Findings:

**NOTE:** If visible evidence of active or previous infestation is reported it should be assumed that some degree of damage is present and a diagram identifying the structure(s) inspected and showing the location of such evidence must be attached to this form. Evaluation of damage and any corrective action should be performed by a qualified inspector in the building trade approved by the purchaser and lending agency.

**TREATMENT**

The above described structure(s) was treated by this company as follows:

| Organism              | Treatment Date | Contract Expiration | Type Treatment (Chemical Barrier, Bait, Wood Treatment) |
|-----------------------|----------------|---------------------|---|
| Subterranean Termites | <u>3/9/05</u>  | <u>8/26/07</u>      | <u>Poracare</u>   |
| Powder Post Beetles   | ---            | ---                 | ---   |
| Wood Boring Beetles   | ---            | ---                 | ---   |
| Dry Wood Termites     | ---            | ---                 | ---   |
| Wood Decaying Fungus  | ---            | ---                 | ---   |

The present treatment warranty(ies) is:

- Transferable to any subsequent owner of the property upon payment of a fee on or before the expiration date.
- Not transferable to any subsequent owner of the property.
- The above structure(s) are not covered by a treatment contract with this company.

This structure has a current Exception Form II issued by this Company  Yes  No  
 If Yes, a copy must be attached as part of this report.

**CERTIFICATION**

This is to certify that neither I, nor the company has had or contemplates having any interest in the property involved, nor is acting in any association with any party to the transaction.

L. Foward Rich Signature of Designated Certified Operator      \_\_\_\_\_ Signature of Purchaser or Legal Representative Acknowledging Receipt of Report

Copies to:  Purchaser       Mortgage       Realtor       Seller

**CONDITIONS GOVERNING THIS REPORT**

1. This report is limited to the five organisms listed.
2. This report covers only those structures listed on the front.
3. Inspection, including sounding and/or probing, was performed in only those areas which were readily accessible. Inaccessible areas not inspected include, but are not limited to areas obstructed by, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances or other personal items. The inspection also included a check of company records to determine if the structure has been treated and/or under renewal contract with the company within the past two years for any of the covered organisms. A copy of any current Exception Form II for this structure must be included as part of this report.
4. Reporting of Wood Destroying Fungi on this report is intended to cover only white rot, brown rot or water conducting fungi (*Poria incrassata*) infestations which occur below the first floor level and which result from moisture conditions which can be corrected through application of moisture barriers and/or increased ventilation and is not intended to cover conditions resulting from roof or plumbing leaks, or improper drainage of surface water. This report does not cover the reporting of molds and mildews. Structural Pest Control companies are not responsible for inspecting for molds.
5. The term Wood Boring Beetles as used on the reverse side means only those beetles which are known to establish and maintain a continuing infestation in structures, such as, but not limited to the Old House Borer.
6. Regardless of whether any visible evidence of infestation by any of the listed Wood Destroying Organisms is found during inspection, if an infestation of one or more of these organisms from which apparent freedom was certified is found within 90 days of issuance of this report the property shall receive, free of charge, a minimum adequate treatment for control of the infestation consistent with Rules 620-6-.03(1)(a), (b), (c), and (d), of the Georgia Structural Pest Control Act. Any condition conducive to infestation as defined in item nine (9) below that is known to have existed at the time of inspection and was not reported and is found within two (2) years from the date of the report shall be corrected free of charge by the licensee.
7. This is not a structural report. A wood destroying organism inspector is not ordinarily a construction or building trade expert and is therefore not expected to assess structural soundness. Evaluation and correction of damage which may have resulted from an active or previous infestation should be performed by a qualified inspector in the building trade, who is approved by the purchaser and the lending agency.
8. This report implies no responsibility on the part of the Georgia Department of Agriculture or the Georgia Structural Pest Control Commission to enforce or require anything other than treatment or retreatment to the minimum adequate treatment requirements specified in Rule 620-6-.04.
9. **Conditions Conducive To Infestation** means conditions that exist in a structure that *favor the development of wood destroying* organisms. These are limited to: cellulosic material underneath a building, wood in contact with the soil which has not been treated with preservatives to a minimum preservative retention designed for ground contact and ventilation that does not meet the requirements specified in Rule 620-6-.04(1)(a)(8).

The format of this report conforms to the Rules of the GEORGIA STRUCTURAL PEST CONTROL COMMISSION, Chapter 620-6-.03, as amended. Printed and distributed, to provide a central source of supply, as a service to the industry by GEORGIA PEST CONTROL ASSOCIATION.

2034 Beaver Run Road  
Norcross, Georgia 30071. 770-417-1881